

Advanced BioTech

Developer of BioWorld Products

Oil Sludge Bioremediation Case Study Bench Scale Test



Oil Sludge from old well drilling pit. Side by side comparison. (See dried lump in tanks.)

Left – Control

Right – Treated with BioWorld Hydrocarbon Treatment Products.



Several days later.
Left (Control) – Water has no signs of biological activity.

Right (Treated) – Respiration from microbes degrading the hydrocarbon very apparent.



Several days later.
Left (Control) – Water has no signs of biological activity.

Right (Treated) – Respiration from microbes degrading the hydrocarbon very apparent.

Fatty Acids forming on surface as hydrocarbon breaks down.

BioWorld Products used:

75014 Bioremediation Enhancer

32086 Hydrocarbon Digester Microbes