

# BioWorld Products

California • USA • Worldwide

## Oil/Water Separator Bioremediation Case Study

Waste oil was about 3 inches thick in a 600 gallon oil/water separator at a tractor repair facility.



3 days after BioWorld Hydrocarbon Treatment, the thick oil was degraded to a fine layer of fatty acids. (The unit was moved outside.)



BioWorld saved this client US\$400 per month in disposal costs.

3 days after BioWorld Hydrocarbon Treatment, the oil was degraded for safe disposal as non-hazardous material.



Oil was about 1 inch thick after treating with BioWorld Hydrocarbon treatment products. The tank was rolled outside.



**BioWorld Products Used:**  
**75014 – Bioremediation Enhancer**  
**32086 – Hydrocarbon Digester Microbes**

[www.bioworldusa.com](http://www.bioworldusa.com) • [mail@bioworldusa.com](mailto:mail@bioworldusa.com) • 559.651.2042

International Headquarters • R&D • Manufacturing • Distribution Center

8244 W Hillsdale Ct • PO Box 2920 • Visalia California 93279-2920 • United States of America

Copyright © 1991-2006. All rights reserved