

# Advanced BioTech

*Developer of MultiFIX™ and BioWorld Products™*

## Oil/Water Separator Bioremediation Case Study

Waste oil was about 3 inches thick in a 600 gallon oil/water separator at a tractor repair facility.




3 days after BioWorld Hydrocarbon Treatment, the thick oil was degraded to a fine layer of fatty acids. (The unit was moved outside.)



BioWorld saved this client US\$400 per month in disposal costs.

3 days after BioWorld Hydrocarbon Treatment, the oil was degraded for safe disposal as non-hazardous material.



Oil was about 1 inch thick after treating with BioWorld Hydrocarbon treatment products. The tank was rolled outside.



**BioWorld Products Used:**  
**75014 – Bioremediation Enhancer**  
**32086 – Hydrocarbon Digester Microbes**